




BAUTEILLISTE			
OBJEKT	ANZAHL	BAUTEILNUMMER	BESCHREIBUNG
1	1	0125-01	
2	1	C-101-01-or-gf-8-1-240	
3	1	DP-106-08	
4	6	Spr-M8-12	35Nm + Glue
5	6	DIN912-M10-1-25	107Nm + Glue

All threads and screws must be thoroughly cleaned before assembly and before applying thread adhesive.

				Datum	Name		
			Gezeichnet	26.02.2026	behni		
			Kontrolliert				
			Norm				
						CK106-01	1
							A2
Status	Änderungen	Datum	Name			2	1